

CHEMATIC[®] 420 USAGE GUIDELINES & BEST PRACTICES

DOBER



RECOMMENDED PPE

- GLOVES
- SAFETY GLASSES WITH SIDE SHIELDS
- PROTECTIVE CLOTHING (LAB COAT OR LONG SLEEVES WITH PROTECTIVE APRON)
- FACE SHIELD (ONLY WHEN SPRAYING WITH HIGH PRESSURE)

TRIMMING ROOM

AREAS/EQUIPMENT	Trays, bins, screens, scissors		
DETERGENT RECOMMENDED	Chematic [®] 420	CONCENTRATION	10-25%

RECOMMENDED CLEANING PROCESS:

STEP	ACTIVITY
1. PREPARE DETERGENT SOLUTION	Measure detergent solution and add to appropriate volume of water to make desired detergent concentration. 10% is recommended for dry residues while 25% is recommended for wet/sticky residues
2. DETERGENT SOAK	Let items soak in the detergent solution for a minimum of 15 minutes.
3. DETERGENT WASH	Wipe surface with rag or scrub pad to remove any remaining visible residue
4. RINSE	Immediately rinse items with ambient temperature water. Do not let detergent solution dry on the surface. Rinse until all detergent solution is removed
5. INSPECTION	Inspect the for any residue after items are dry.

CHEMATIC® 420 USAGE GUIDELINES & BEST PRACTICES

DOBER



TRIMMING ROOM BEFORE AND AFTER EXAMPLE PHOTOS



CHEMATIC® 420 USAGE GUIDELINES & BEST PRACTICES

DOBER



NURSERY ROOM

AREAS/EQUIPMENT	Trays, bins, racks, walls, floors		
DETERGENT RECOMMENDED	Chematic® 420	CONCENTRATION	25%



RECOMMENDED CLEANING PROCESS:

STEP	ACTIVITY
1. PREPARE DETERGENT SOLUTION	Measure detergent solution and add to appropriate volume of water to make desired detergent concentration. 25% is recommended as a starting dilution
2. DETERGENT SPRAY	Depending on the size of the area to be cleaned, use a spray bottle, or spray system for application. Spray surface of area to be cleaned with detergent solution until it is saturated with detergent solution
3. DETERGENT SOAK	Let the detergent remain on the surface for 10-15 minutes
4. DETERGENT WASH	Clean with brushes, mops, or scrub pads to remove any remaining visible residue
5. RINSE	Immediately rinse items with ambient temperature water. Do not let detergent solution dry on the surface. Rinse until all detergent solution is removed
6. INSPECTION	Inspect the for any residue after items are dry.

CHEMATIC® 420

USAGE GUIDELINES & BEST PRACTICES

DOBER



NURSERY ROOM BEFORE AND AFTER EXAMPLE PHOTOS



CHEMATIC[®] 420 USAGE GUIDELINES & BEST PRACTICES

DOBER



PLANT ROOM

AREAS/EQUIPMENT	Trays, bins, racks, walls, floors		
DETERGENT RECOMMENDED	Chematic [®] 420	CONCENTRATION	25%

RECOMMENDED CLEANING PROCESS:

STEP	ACTIVITY
1. PREPARE DETERGENT SOLUTION	Measure detergent solution and add to appropriate volume of water to make desired detergent concentration. 25% is recommended as a starting dilution
2. DETERGENT SPRAY	Depending on the size of the area to be cleaned, use a spray bottle, or spray system for application. Spray surface of area to be cleaned with detergent solution until it is saturated with detergent solution
3. DETERGENT SOAK	Let the detergent remain on the surface for 10-15 minutes
4. DETERGENT WASH	Clean with brushes, mops, or scrub pads to remove any remaining visible residue
5. RINSE	Immediately rinse items with ambient temperature water. Do not let detergent solution dry on the surface. Rinse until all detergent solution is removed
6. INSPECTION	Inspect the for any residue after items are dry.

CHEMATIC® 420

USAGE GUIDELINES & BEST PRACTICES

DOBER



PLANT ROOM BEFORE AND AFTER EXAMPLE PHOTOS



CHEMATIC® 420 USAGE GUIDELINES & BEST PRACTICES

DOBER



DRYING ROOM

AREAS/EQUIPMENT	Trays, bins, racks, walls, floors		
DETERGENT RECOMMENDED	Chematic® 420	CONCENTRATION	25%

RECOMMENDED CLEANING PROCESS:

STEP	ACTIVITY
1. PREPARE DETERGENT SOLUTION	Measure detergent solution and add to appropriate volume of water to make desired detergent concentration. 25% is recommended as a starting dilution
2. DETERGENT SPRAY	Depending on the size of the area to be cleaned, use a spray bottle, or spray system for application. Spray surface of area to be cleaned with detergent solution until it is saturated with detergent solution
3. DETERGENT SOAK	Let the detergent remain on the surface for 10-15 minutes
4. DETERGENT WASH	Clean with brushes, mops, or scrub pads to remove any remaining visible residue
5. RINSE	Immediately rinse items with ambient temperature water. Do not let detergent solution dry on the surface. Rinse until all detergent solution is removed
6. INSPECTION	Inspect the for any residue after items are dry.

CHEMATIC® 420

USAGE GUIDELINES & BEST PRACTICES

DOBER



DRYING ROOM BEFORE AND AFTER EXAMPLE PHOTOS